



DO NOT DISCARD: IMPORTANT SAFETY NOTICE MaxJax- 2 Post Portable Lift

Failure to read, understand and follow these instructions may cause death or serious injury.

Technical Service Bulletin (TSB) No. 000456

Date: 01/23/2015

POTENTIAL CONCERN: Lower carriage plate(s) may have been insufficiently welded to the inside of the carriage.

Dear Valued Customer:

You are receiving this letter in regard to your recent purchase of a Dannmar™ MaxJax™ 2 Post Portable Lift with a date of manufacture 09/2/2014 thru 1/14/2015. As you know, Dannmar Equipment takes great pride in the quality of its products. Our commitment to excellence means that we work hard to ensure that every item in our inventory meets the highest reliability, durability, and safety standards. With this in mind, we are writing to you regarding a potential issue recently discovered with the lift head carriage assembly.

Although no one has been hurt, our review of the welding reveals that the block on the lift head carriage may not have adequate welds. While this problem impacts only a very small number of the Dannmar MaxJax Two Post Portable Lifts sold by Dannmar Equipment Inc, we regret that your particular unit purchased from September 2, 2014 thru January 14, 2015 from our reputable distributors is part of the lot in which this problem may occur. We are in touch with all of our partners to address this situation and will make every effort to replace these components free of charge as soon as possible.

In the meantime, <u>Dannmar Equipment strongly recommends that you immediately cease using your Dannmar™</u>
<u>MaxJax™ 2 Post Portable Lift until further notice.</u> We apologize for this inconvenience. If you have any questions contact
Dannmar by phone at 1-877-432-6627, by email at <u>support@dannmar.com</u>, or visit our web site at: <u>www.dannmar.com</u>.

Very Truly Yours,

Marco Ortiz

General Manager/Sales Director