

Safety Recall

evenflo Embrace 35 Infant Child Restraints

**PRODUCTS CURRENTLY OFFERED FOR SALE AT THIS RETAILER
ARE NOT SUBJECT TO THIS RECALL.**



Model Numbers: 30711365, 31511040, 31511323, 31511400, 3151198, 3151953, 31521138, 46811205, 46811237, 48111200, 48111215, 48111215A, 48111218, 48111234, 48111235, 48111235A, 48111462, 48411391, 48411391D, 48411392, 48411504, 48411504D, 52911307A, 52921040, 55311138, 55311238, and 55311292
Date of Manufacture: Various from December 1, 2011—May 31, 2013***

Select Embrace 35 models manufactured in the December 1, 2011—May 31, 2013 date range use a harness crotch buckle which may become difficult to unlatch over time, due to exposure to various contaminants (like food and drinks). This condition may make it challenging to remove a child from car seat, increasing the risk of injury in the event of an emergency situation where prompt exit of the vehicle is necessary. There is no such risk if the buckle is functioning normally. These car seats continue to meet or exceed all requirements for crashworthiness under the federal FMVSS 213 safety standard and can still be used to transport your child safely, if you are not experiencing difficulty unlatching the buckle.

*****Not all Embrace 35 models in the December 1, 2011—May 31, 2013 date range are impacted.** Consumers who believe they may own a car seat subject to this recall should visit the recall website or call Evenflo's toll-free number for a free remedy kit of a replacement buckle. Recalled units should not be returned to the retailer.

www.embracebuckle.evenflo.com

1-800-490-7591 (8am – 5pm EST)

This recall is being done in cooperation with the National Highway Traffic Safety Administration (Recall #14C-006).

Please post until February 19, 2015